

Oil Field Environmental Incident Summary

Incident: 20140814101136 **Date/Time of Notice:** 08/14/2014 10:11

Responsible Party: CONDOR PETROLEUM, INC.

Well Operator: CONDOR PETROLEUM, INC.

Well Name: PETERSON 18-2

Field Name: NORTH TIOGA

Well File #: 13669

Date Incident: 8/14/2014 **Time Incident:** 05:30

Facility ID Number:

County: BURKE

Twp: 159

Rng: 94

Sec: 18

Qtr:

Location Description:

Submitted By: Emily Drabbs

Received By:

Contact Person: Dave Heilman
216 16TH STREET SUITE 1750
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 5 Mile

Distance Nearest Water Well: 5 Mile

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	90	Barrels	90	Barrels		
Other					90	barrels

Description of Other Released Contaminant:

[Redacted area]

Inspected:

Written Report Received: 10/6/2015

Clean Up Concluded: 8/15/2014

Risk Evaluation:

n/a

Areal Extent:

Potential Environmental Impacts:

none-contained within dike

Action Taken or Planned:

salt water sucked out of dike and taken to disposal. power fuels came to haul salt water out of tank. will need to wash out dike.

Wastes Disposal Location: Nearby salt water disposal.

Agencies Involved:

Updates

Date: 8/14/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, remained on location within the diking according to the report. NDIC retains oversight.