

Oil Field Environmental Incident Summary

Incident: 20140915110717 **Date/Time of Notice:** 09/15/2014 11:07
Responsible Party: SAKAKAWEA VENTURES, LLC
Well Operator: SAKAKAWEA VENTURES, LLC
Well Name: SV MCGREGOR 1
Field Name: SAUK **Well File #:** 90235
Date Incident: 9/9/2014 **Time Incident:** 01:15 **Facility ID Number:**
County: WILLIAMS **Twp:** 159 **Rng:** 95 **Sec:** 21 **Qtr:** NW NW
Location Description: SV MCGREGOR 1

Submitted By: Chris Valenti **Received By:**
Contact Person: Jack Roe
1820 Platte Street
DENVER, CO 80202-1288

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 1.7 Mile
Distance Nearest Water Well: 1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	5	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

Spill was discovered immediately, manually shut-down, remediated with a vacuum truck and material was sent back through the SWD system.

Areal Extent:

Potential Environmental Impacts:

None.

Action Taken or Planned:

Require that operators manually close valves during power failure if tank levels are above 15 feet.

Wastes Disposal Location: At the Class II disposal well SV McGregor 1 where the spill occurred.

Agencies Involved: NA

Updates

Date: 9/15/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.