

Oil Field Environmental Incident Summary

Incident: 20140928095055 **Date/Time of Notice:** 09/28/2014 09:50

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: CLEARWATER 200-06 SWD

Field Name: CLEAR WATER

Well File #: 90180

Date Incident: 9/27/2014 **Time Incident:** 19:05

Facility ID Number:

County: MOUNTRAIL

Twp: 157

Rng: 90

Sec: 6

Qtr: SW SE

Location Description:

Submitted By: Keith Kallberg

Received By:

Contact Person: Keith Kallberg
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	7	Barrels	7	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Low

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

The sump pump was shut down to the transfer line. A vac truck was called in to remove the free standing fluid, fresh water will be used to flush the affected area 2 x and the fluids removed. The line will be inspected and replaced.

Wastes Disposal Location: Fluids will be put back into the Clearwater SWD.

Agencies Involved:

Updates

Date: 9/29/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an unspecified cause, remained on location within the diking according to the report. NDIC retains oversight.