

Oil Field Environmental Incident Summary

Incident: 20141017213042 **Date/Time of Notice:** 10/17/2014 21:30
Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC
Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC
Well Name: ALVIN 14-7H-1819-15895-TF
Field Name: TEMPLE **Well File #:** 26624
Date Incident: 10/17/2014 **Time Incident:** 09:00 **Facility ID Number:**
County: WILLIAMS **Twp:** 158 **Rng:** 95 **Sec:** 7 **Qtr:**

Location Description:

Submitted By: James Shaw **Received By:**
Contact Person: James Shaw
1200 17TH STREET, SUITE 2050
DENVER, CO 80202

General Land Use: Cultivated **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Vessel Leak

Release Contained in Dike: Yes - On Facility Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine 1 Barrels

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

None

Areal Extent:

Seeped 5 ft from SE corner of vessel containment system, approximately 20 ft along edge (100 sq-ft).

Potential Environmental Impacts:

None

Action Taken or Planned:

Remove and replace affected soil. Repair liner failure in containment, test with fresh water.

Wastes Disposal Location: Haul to a commercial disposal site.

Agencies Involved:

Updates

Date: 10/18/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a vessel leak, remained on location according to the report. NDIC retains oversight.