

Oil Field Environmental Incident Summary

Incident: 20141118160309 **Date/Time of Notice:** 11/18/2014 16:03

Responsible Party: SAKAKAWEA VENTURES, LLC

Well Operator: SAKAKAWEA VENTURES, LLC

Well Name: SV MCGREGOR 1

Field Name: SAUK

Well File #: 90235

Date Incident: 11/14/2014 **Time Incident:** 10:30

Facility ID Number:

County: WILLIAMS

Twp: 159

Rng: 95

Sec: 21

Qtr:

Location Description:

Submitted By: Stanley Roe

Received By:

Contact Person: Stanley Roe
1830 BLAKE STREET
DENVER, CO 80202-1288

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels	3	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Low risk

Areal Extent:

Potential Environmental Impacts:

Low volume and quickly cleaned up. Minimal impact.

Action Taken or Planned:

Closer monitoring of 3rd party service providers.

Wastes Disposal Location: Recovered waste was pumped into storage tank on site.

Agencies Involved:

Updates

Date: 11/18/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping connection leak, remained on location according to the report. NDIC retains oversight.