

Oil Field Environmental Incident Summary

Incident: 20141207112806 **Date/Time of Notice:** 12/07/2014 11:28

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: CLEARWATER 1-02H

Field Name: CLEAR WATER

Well File #: 17151

Date Incident: 12/6/2014 **Time Incident:** 11:30

Facility ID Number:

County: MOUNTRAIL

Twp: 157

Rng: 90

Sec: 2

Qtr:

Location Description: North of flare pit off location.

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Popoff

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Gallons	2	Gallons	2	gallons

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/19/2015

Clean Up Concluded: 12/7/2014

Risk Evaluation:

N/A

Areal Extent:

20ft x 100 ft oil mist off location on top of snow and onsite area near flarepit.

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Offsite oil misted snow area was removed by shoveling and the snow was brought back onto location and remediated onsite. Landowner contact has not been made via phone calls but will continue to try to make contact.

Wastes Disposal Location: Remediated onsite

Agencies Involved:

Updates

Date: 12/8/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spray off location due to a treater popoff valve opening. Plume may have originated from the flare. Followup is necessary.

Date: 12/10/2014 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Site inspected. Cleanup has occurred with hand shoveling on landowner property. Spoke to company representative by phone, and rep indicated attempts had been made to contact the landowner but had been unsuccessful so far. Cows are present in the field as this is pasture land. No spray off well pad was apparent at time of inspection. Follow up to verify landowner contact and if company is finished with cleanup or will take equipment into the field.

Date: 9/3/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

No sign of impact or remaining contaminants at the time of inspection. There is a wetland in the described impact area; however, there aren't any signs of impacts on wetland.

No followup is necessary.

Date: 4/18/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated April 18, 2016.