

Oil Field Environmental Incident Summary

Incident: 20141211185125 **Date/Time of Notice:** 12/11/2014 18:51

Responsible Party: BOH LLC

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: HOLTE 2-32H

Field Name: STONEVIEW

Well File #: 28084

Date Incident: 12/11/2014 **Time Incident:** 01:30

Facility ID Number:

County: DIVIDE

Twp: 160

Rng: 95

Sec: 32

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Kelly Martinez
13745 55th St Nw
Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.5	Barrels	1.4	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Minimal after clean-up.

Action Taken or Planned:

Absorbent pads were used to clean-up standing fluid, and impacted soil and material will be removed and taken to Indian Hills Disposal.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved: Notified Tom Delling NDIC by phone on 12/11/2014 at 4:30 PM.

Updates

Date: 12/12/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an apparent truck tank leak, remained on location according to the report. NDIC retains oversight.