

Oil Field Environmental Incident Summary

Incident: 20141218163116 **Date/Time of Notice:** 12/18/2014 16:31

Responsible Party: NEWFIELD PRODUCTION COMPANY

Well Operator: NEWFIELD PRODUCTION COMPANY

Well Name: HOLM 150-99-13-24-2H

Field Name: SIVERSTON

Well File #: 25271

Date Incident: 12/18/2014 **Time Incident:** 08:10

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 99

Sec: 13

Qtr:

Location Description:

Submitted By: Tim Eaton

Received By:

Contact Person: Tim Eaton
363 N. SAM HOUSTON, PKWY E
SUITE 100
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	15	Barrels	15	Barrels	15	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/7/2015

Clean Up Concluded: 12/22/2014

Risk Evaluation:

Impact to location soils as the oil froze in place. Some misting on reclaimed area.

Areal Extent:

150' x 200'

Potential Environmental Impacts:

Only to location soils.

Action Taken or Planned:

Shut well in and attempt to recover as much oil as possible. Oil froze in place on location.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 12/19/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, remained on location according to the report. NDIC retains oversight.