

# Oil Field Environmental Incident Summary

**Incident:** 20141231133122      **Date/Time of Notice:** 12/31/2014 13:31

**Responsible Party:** MELISSA HOLT

**Well Operator:**

**Well Name:**

**Field Name:**

**Well File #:**

**Date Incident:** 12/31/2014      **Time Incident:** 02:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 129

**Rng:** 60

**Sec:** 1

**Qtr:**

**Location Description:** I am unsure what "township, range and section" mean so I just put the lowest quantity..... To get to the spill you take Co Rd 57 South, Go Approximately 5.3 miles. You will see a road to the left. The spill is on the right side of the road, right before you get to that road.

**Submitted By:** MELISSA HOLT

**Received By:**

**Contact Person:** MELISSA HOLT  
109 6TH AVE SE #4577  
WATFORD CITY, ND 58854

**General Land Use:** Badlands Terrain

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Leak

**Release Contained in Dike:** No

**Reported to NRC:** Yes

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	140	Barrels	135	Barrels		
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No Risks. It opened far away from any one or anything.

**Areal Extent:**

small area

**Potential Environmental Impacts:**

Extremely unlikely to have any impacts. The salt water pooled on the surface and was sucked up. The contaminated site is a ditch off the side of the road. The vast majority of it was sucked up. No houses or living facilities within the immediate area.

**Action Taken or Planned:**

The spill happened in a ditch off the side of the road. Within a few minutes a tanker was there sucking up the leaked salt water. Shortly there after a second tanker helped sucked up any remaining salt water. The police were called, and an environmental lady showed up to look over the contaminated area. We have a clean up crew in route to assess the damage, and prepare to take necessary actions to clean up.

**Wastes Disposal Location:** The vac tankers disposed of the sucked up salt water to 1804 Berwarld Disposal located on CoRd 57 South.

**Agencies Involved:** Local Law Enforcement

**Updates**

---

**Date:** 12/31/2014 **Status:** Inspection

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site at 9:48 a.m. on 12/31/14. Impacted area was to the ditch on the SW side of road. There is some pooling of a green-tinged fluid in the ditch. There are also some piping and valves from the truck in the ditch. Area of impact is approximately 90 X 15 ft. There is a small area of impact on County Road 57. Spoke to contact person and was told most of spill was sucked up shortly after spill occurred. They are working on getting a cleanup crew to the site for further cleanup. More followup is required.

---

**Date:** 12/31/2014 **Status:** Reviewed - Follow-up Required

**Author:** Washek, Sandi

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Truck and tanker trailer rollover with loss of production water into roadside ditch. Followup required.

---

**Date:** 1/6/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site at 10:27 a.m. The area received snow yesterday. Overcast with winds from the northwest 10 mph with a temperature -0°F. The accident occurred in 149-95-16; as indicated the accident occurred on the west side of road. The truck hitch plate was still lying in the ditch; the other materials have been hauled away. South of the drainage is a brush patch that has been disturbed. The area is cover by 2-3 inches of snow. More followup needed. 47.732383; -102.849700

---

**Date:** 6/3/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site at 10:51 a.m. The weather was clear, 54°F, with the wind from the northeast 5-10 mph. There is water standing in the ditch, and vegetation is growing (including wetland vegetation). The drainage under the road and going west looks normal. Booms in the area still needed to be removed. No further followup needed at this time. 47.73241; - 102.84802

---

**Date:** 6/4/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Requested more information on the spill.