

Oil Field Environmental Incident Summary

Incident: 20150103132649 **Date/Time of Notice:** 01/03/2015 13:26

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PARSHALL 20-03H

Field Name: PARSHALL

Well File #: 16986

Date Incident: 1/3/2015 **Time Incident:** 08:10

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 90

Sec: 3

Qtr:

Location Description:

Submitted By: Matt Richards

Received By:

Contact Person: Matt Richards
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	10	Barrels	10	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/27/2015

Clean Up Concluded: 1/9/2015

Risk Evaluation:

N/A

Areal Extent:

600' x 300'

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Contaminated snow/material will be removed from the location and off site contaminated materials will be remediated as the surface owner wishes. When temperatures begin to warm the pumping unit will be cleaned off.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 1/5/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 1/7/2015 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/7/2015 at 14:30, on location. Partial cleanup visible. Pile of impacted snow and wheat stubble next to empty rolloff near visibly stained pump jack along southern edge of wellpad. Wheat stubble hill slope to the southwest has been bladed to remove wheat stubble and snow, but it has not been scraped. Some staining still visible in bladed area, as well as a snow-bermed area of heavily impacted snow south of the pumpjack. Called report contact. Contact indicated heavily impacted snow is going to be hydrovac'd out, and impacted snow/wheat stubble will be loaded into rolloff. Landowner did not want topsoil disturbed, so field was not scraped. Requested signed letter from company and landowner to confirm.

Date: 9/2/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 10:44 9/1/2015.

This year's crop looks good and has been harvested. There were no signs of impact at the time of inspection.

No followup is necessary.

Date: 4/18/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated April 18, 2016.