

Oil Field Environmental Incident Summary

Incident: 20150109164348 **Date/Time of Notice:** 01/09/2015 16:43

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: ALPHA 3-14H

Field Name: CAMP

Well File #: 21979

Date Incident: 1/9/2015 **Time Incident:** 05:00

Facility ID Number:

County: MCKENZIE

Twp: 152 **Rng:** 100 **Sec:** 14 **Qtr:**

Location Description:

Submitted By: Justin Collins

Received By:

Contact Person: Darrell Berglund
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Popoff

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3.5	Barrels	3.5	Barrels	3.5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/3/2016

Clean Up Concluded: 1/16/2015

Risk Evaluation:

None

Areal Extent:

Misted 900' x 100' area in pasture.

Potential Environmental Impacts:

Well site soil/snow, pasture soil/snow

Action Taken or Planned:

Remove misted snow from pasture and put into flare pit. Remove some contaminated material from location and take to disposal.

Wastes Disposal Location: Indian Hill Disposal

Agencies Involved:

Updates

Date: 1/9/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted an area off of location. Followup is necessary.

Date: 1/29/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 12:52 p.m. The weather was clear, 25 °F with wind from the northwest at 5-10 mph. The snow has melted in the area, but the ground was frozen. The area impacted was on the east side of the well pad. Both the side slope of the well pad and the pasture had been mowed and raked. There are a couple of areas where the root balls of the vegetation were stained. More followup required. 47.989000, - 103.438517

Date: 4/9/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 9:43 a.m. The weather was clear, 41 °F, with the wind from the northwest at 10-15 mph. The pasture grass is greening up; there are a couple of stained areas. No further followup needed.

Date: 3/9/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 9, 2016.