

Oil Field Environmental Incident Summary

Incident: 20150122162318 **Date/Time of Notice:** 01/22/2015 16:23

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: CORNABEAN 156-101-25-36-1H

Field Name: TYRONE

Well File #: 21481

Date Incident: 1/22/2015 **Time Incident:** 15:30

Facility ID Number:

County: WILLIAMS

Twp: 156 **Rng:** 101 **Sec:** 36 **Qtr:**

Location Description: Northeast of flare pit, 25 yards long by 15 yards wide

Submitted By: Sadie Fliegel

Received By:

Contact Person: Sadie Fliegel
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.3 Mile

Distance Nearest Water Well: 0.3 Mile

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels			2	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/2/2015

Clean Up Concluded: 1/23/2015

Risk Evaluation:

None Noted

Areal Extent:

Light mist covered an area of 25 yards long by 15 yards wide.

Potential Environmental Impacts:

None Noted

Action Taken or Planned:

Impacted snow and soil will be scraped up and pulled back into containment.

Wastes Disposal Location: Impacted snow and soil will be brought to an appropriate disposal.

Agencies Involved:

Updates

Date: 1/22/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 2/6/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 16:02 2/4/2015.

Light spray to the NE of flare. At the time of inspection, another spray from the flare had just occurred. New spill was yet to be reported at the time of inspection and was also yet to be cleaned up.

More followup is necessary as this is the third spill from this location in a year and a half.

Date: 10/12/2015 **Status:** Correspondence

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

A meeting was held in January 2015 to meet with Whiting Oil and Gas about frequent spills on sites that were obtained from Kodiak.

No follow-up is necessary.