

# Oil Field Environmental Incident Summary

**Incident:** 20150126131205      **Date/Time of Notice:** 01/26/2015 13:12

**Responsible Party:** NEWFIELD PRODUCTION COMPANY

**Well Operator:** NEWFIELD PRODUCTION COMPANY

**Well Name:** SAND CREEK FEDERAL 153-96-23-14-3H

**Field Name:** KEENE

**Well File #:** 21592

**Date Incident:** 1/25/2015      **Time Incident:** 11:45

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 153

**Rng:** 96

**Sec:** 26

**Qtr:** NW NW

**Location Description:**

**Submitted By:** Tim Eaton

**Received By:**

**Contact Person:** Tim Eaton  
363 N. SAM HOUSTON, PKWY E  
SUITE 100  
HOUSTON, TX 77060

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	25	Barrels	25	Barrels	25	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 2/6/2015

**Clean Up Concluded:** 1/29/2015

**Risk Evaluation:**

Only to facility soils.

**Areal Extent:**

**Potential Environmental Impacts:**

Only to facility soils.

**Action Taken or Planned:**

Liquids were contained within diked area and were vacuumed up then returned to the tanks on location. A super sucker will remove affected soils within the diked area and take them to disposal. Fresh gravel will be brought in. The burn tube will be replaced and likely the anode as well.

**Wastes Disposal Location:** Liquids were returned to the tanks on location and the contaminated gravel will go to Bakken Western disposal.

**Agencies Involved:** BLM and USFS

**Updates**

---

**Date:** 1/26/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.