

Oil Field Environmental Incident Summary

Incident: 20150210213645 **Date/Time of Notice:** 02/10/2015 21:36

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: PEERY STATE 12-25TFH

Field Name: SANISH

Well File #: 25917

Date Incident: 2/10/2015 **Time Incident:** 18:00

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 92

Sec: 25

Qtr: NW SW

Location Description: Majority of release remained on location with less than 0.5 bbls of oil misting to the southeast off location impacting an area approximately 100' by 30'

Submitted By: Brian Wurm

Received By:

Contact Person: Brian Wurm
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels	1	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/4/2015

Clean Up Concluded: 2/16/2015

Risk Evaluation:

None noted

Areal Extent:

Approximately 100' by 30' to the southeast off location

Potential Environmental Impacts:

None noted

Action Taken or Planned:

A vac truck was brought in to pick up impacted material on location.

Wastes Disposal Location: Impacted material will be taken to appropriate disposal.

Agencies Involved:

Updates

Date: 2/11/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted the surrounding location. Followup is necessary.

Date: 2/27/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spill report states 100- X 30-foot area SE off location. Inspection noted apparent excavation/scraping areas. No oil seen.