

Oil Field Environmental Incident Summary

Incident: 20150220090857 **Date/Time of Notice:** 02/20/2015 09:08

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: MAWSON 5493 43-23T

Field Name: ROBINSON LAKE

Well File #: 25640

Date Incident: 2/18/2015 **Time Incident:** 19:15

Facility ID Number:

County: MOUNTRAIL

Twp: 154

Rng: 93

Sec: 23

Qtr: SW SE

Location Description: Production Location

Submitted By: Dan Grafton

Received By:

Contact Person: Dan Grafton
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	9	Barrels	9	barrels
Brine	5	Barrels	4	Barrels	4	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/26/2016

Clean Up Concluded: 5/12/2015

Risk Evaluation:

low

Areal Extent:

Potential Environmental Impacts:

low--soil

Action Taken or Planned:

Review process

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 2/22/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 2/22/2014.

Extent of spill has been scraped up and stockpiled and is awaiting disposal. A vast majority of the spill has been cleaned up except for the area on the impacted Hess wellsite. The Oil and Gas inspector for the area has been notified of the area on the Hess location that hasn't been cleaned up.

More followup in the spring is necessary to ensure proper cleanup.

Date: 2/23/2015 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an unspecified cause, did not remain on location within the diking according to the report. Followup is necessary.

Date: 4/24/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 12:00 4/7/2015.

Spill has been scraped up and removed. Request company to provide a cleanup summary for this incident.

More followup is necessary.

Date: 5/12/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 15:25 5/12/2015.

No residual impacts to areas off of location. Grass is coming in nicely, and impacted trees are budding out.

A No Further Action letter has been issued.

No followup is necessary.