

Oil Field Environmental Incident Summary

Incident: 20150221184613 **Date/Time of Notice:** 02/21/2015 18:46

Responsible Party:

Well Operator: LEGACY OIL & GAS ND, INC.

Well Name: SCANDIA CTB

Field Name: SOURIS

Well File #:

Date Incident: 2/21/2015 **Time Incident:** 07:46 **Facility ID Number:** 223487-01

County: BOTTINEAU **Twp:** 164 **Rng:** 78 **Sec:** 34 **Qtr:** NE NE

Location Description: Spill contained on well site.

Submitted By: Jeremy Yeglin

Received By:

Contact Person: Jim Gordon
4400, 525-8TH AVENUE SW
CALGARY, AB T2P 1g1

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	50	Barrels	10	Barrels		
Brine	50	Barrels	10	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Fire was extinguished and spill contained on site. No immediate hazard.

Areal Extent:

Potential Environmental Impacts:

Soil / snow and surface water contamination.

Action Taken or Planned:

Fire was extinguished and spill contained on well pad. Roads were blocked off during response. Free liquids were vacuumed up and top layer of impacted snow / soil was scraped off and stockpiled for disposal. Samples for analytical testing were taken from impacted materials. Further remediation to be determined upon lab testing results.

Wastes Disposal Location: TBD

Agencies Involved: Local Fire Department - Souris and Bottineau Fire Departments. Scott Ladner with NDIC was verbally notified.

Updates

Date: 2/21/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. However, the report states that surface water could be contaminated. Followup is necessary.

Date: 2/22/2015 **Status:** Correspondence

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the NDIC inspector for the area, this spill remained on the lease location. NDIC retains oversight.