

# Oil Field Environmental Incident Summary

**Incident:** 20150310140812      **Date/Time of Notice:** 03/10/2015 14:08

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** GN-NJOS- 159-98-2635H-1

**Field Name:** BIG STONE

**Well File #:** 28092

**Date Incident:** 3/10/2015      **Time Incident:** 05:20

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 159      **Rng:** 98      **Sec:** 26      **Qtr:**

**Location Description:** The release occurred approximately .5 miles east of the location "GN NJOS 159-98-2635 H1. From HWY 50 travelling eastbound southside of the HWY.

**Submitted By:** Alex Beach

**Received By:**

**Contact Person:** Jason Henry  
1501 MCKINNEY  
HOUSTON, TX 77010

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.8 Mile

**Distance Nearest Water Well:** 0.8 Mile

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	10	Barrels				

**Description of Other Released Contaminant:**

Fresh Water

**Inspected:**

**Written Report Received:** 9/24/2015

**Clean Up Concluded:** 3/10/2015

**Risk Evaluation:**

no immediate risk to report at this time

**Areal Extent:**

the estimated area was 50' x 10'

**Potential Environmental Impacts:**

potential for impacts to topsoil and possible erosion issue

**Action Taken or Planned:**

The line was isolated and excess pressure was relieved. The failed section of piping was removed from service and replaced before operations resumed.

**Wastes Disposal Location:** no waste to report at this time

**Agencies Involved:**

**Updates**

---

**Date:** 3/11/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted the surrounding area. Followup is necessary.

---

**Date:** 3/31/2015    **Status:** Awaiting Documentation

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

3/31/2015 at 18:30, on location. Area between south ditch of Highway 50 and pipeline row further to south has some standing water. Left message with report contact to confirm location and to determine if water is from release or recent rainfall.

---

**Date:** 6/25/2015    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

6/25/2015 at 10:25 am., at location indicated in map supplied by report contact. No visible stress to vegetation in county road ditch.