

Oil Field Environmental Incident Summary

Incident: 20150311210202 **Date/Time of Notice:** 03/11/2015 21:02

Responsible Party: HRC OPERATING, LLC

Well Operator: HRC OPERATING, LLC

Well Name: FORT BERTHOLD 148-95-26B-35-3H

Field Name: EAGLE NEST

Well File #: 27456

Date Incident: 3/11/2015 **Time Incident:** 02:00

Facility ID Number:

County: DUNN

Twp: 148 **Rng:** 95 **Sec:** 26 **Qtr:** NE NW

Location Description: The dump failed on a treater causing it to high level with fluid which then sent fluid to the flare. The flare caught up to 9000 square feet of native vegetation, primarily small trees and scrub, on fire which burned out relatively quickly. The fire was offsite to the north of the well pad. Personnel on site got a water truck to the location, but all that was left smoldering were two wooden fence posts. The rest of the forest litter on the ground and a small amount of wooden stumps were self-extinguished.

Submitted By: Julia Traster

Received By:

Contact Person: Chris Martinez
1801 CALIFORNIA STREET
SUITE 3500
DENVER, CO 80202

General Land Use: Badlands Terrain

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Gallons			5	gallons

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/7/2016

Clean Up Concluded: 3/15/2015

Risk Evaluation:

Low health hazard.

Areal Extent:

9000 square feet

Potential Environmental Impacts:

surface runoff could cause soil erosion, plant mortality due to fire.

Action Taken or Planned:

Burn area will be treated with S200 "Oil Gone". Slope stabilization will be installed.

Wastes Disposal Location: Any waste will be disposed of as per state regulations.

Agencies Involved:

Updates

Date: 3/12/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred within the MHA Nation boundaries. Forward to BIA/Tribal authorities.