

Oil Field Environmental Incident Summary

Incident: 20150329091930 **Date/Time of Notice:** 03/29/2015 09:19

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: MIRAMAR 1-32AH

Field Name: ELK

Well File #: 21601

Date Incident: 3/28/2015 **Time Incident:** 14:00

Facility ID Number:

County: MCKENZIE

Twp: 152 **Rng:** 102 **Sec:** 32 **Qtr:**

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Shane Knuchel
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels	0.1	Barrels	0.5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 5/18/2015

Clean Up Concluded: 3/29/2015

Risk Evaluation:

None

Areal Extent:

150x25 foot path of topsoil and vegetation off the north side of the location was misted.

Potential Environmental Impacts:

Vegetation and top soil.

Action Taken or Planned:

Vegetation will be mowed and bagged, and soil scrapping may occur.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved: Notified Tami Cook NDIC on call inspector at 9:00 AM CT 3/29/2015

Updates

Date: 3/30/2015 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spray off location into cultivated field due to unspecified cause. Followup is necessary.

Date: 4/1/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 16:38 p.m. The weather was cloudy and 52°F, with the wind from the northwest at 5-10 mph. A strip of soil has been removed north of the flare. I did not see any staining of oil in stubble near the stripped area. No further followup required at this time. 47.93601, -103.76353

Date: 5/27/2015 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received the follow-up report and confirmation sampling laboratory report. Based on the data, no further action is warranted.

Date: 3/10/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 10, 2016.