

# Oil Field Environmental Incident Summary

**Incident:** 20150407141413      **Date/Time of Notice:** 04/07/2015 14:14

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** AGNES 1-22H

**Field Name:** UPLAND

**Well File #:** 20576

**Date Incident:** 4/7/2015

**Time Incident:** 13:01

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 161

**Rng:** 96

**Sec:** 22

**Qtr:**

## Location Description:

**Submitted By:** Timothy Ilse

**Received By:**

**Contact Person:** Jon Breeding  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

|              | <b>Spilled</b> | <b>Units</b> | <b>Recovered</b> | <b>Units</b> | <b>Followup</b> | <b>Units</b> |
|--------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| <b>Oil</b>   | 2.5            | Barrels      | 2.5              | Barrels      | 2.5             | barrels      |
| <b>Brine</b> | 2.5            | Barrels      | 2.5              | Barrels      | 2.5             | barrels      |

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/10/2017

**Clean Up Concluded:** 4/7/2015

**Risk Evaluation:**

None

**Areal Extent:**

5 ft. by 10 ft. area

**Potential Environmental Impacts:**

Well site soil

**Action Taken or Planned:**

Liquid was sucked up and put back into production, contaminated material will be removed and replaced with clean fill.

**Wastes Disposal Location:** Prairie Disposal

**Agencies Involved:** Called John Axtman @ 14:00 on 4/7/2015

**Updates**

---

**Date:** 4/7/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.