

Oil Field Environmental Incident Summary

Incident: 20150511193935 **Date/Time of Notice:** 05/11/2015 19:39

Responsible Party: Nivaldo Oliveira

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 5/10/2015 **Time Incident:** 14:30

Facility ID Number:

County: DUNN

Twp: 133 **Rng:** 60 **Sec:** 1 **Qtr:**

Location Description: This happened on highway 22 in the canyon at about mile 133

Submitted By: Jason Buckman

Received By:

Contact Person: Eric Fennell
4111 NW 12th ave
Camas, WA 98607

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine	30	Gallons				
--------------	-----------	----------------	--	--	--	--

Other

Description of Other Released Contaminant:

This was production water that was pulled from a well location off of the reservation.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Heavy Salt water, no streams near by. most of it evaporated as it spread across the pavement

Areal Extent:

spills ended up covering about a 50 sq yard area of highway.

Potential Environmental Impacts:

There is salt on the highway, it made it across the high way and covering a large area, At that spot there is hill and its on a comer it slopes to the east. some of the water made it to the gravel. shoulder.

Action Taken or Planned:

The driver that started this chain reaction has been terminated. The other driver has been written up, That driver has been taught how a vacuum trailer works. I will be giving a explanation of what went wrong during this procedure and how this should have been done so there was no spills. This will happen Tuesday May 12th at the monthly safety meeting.

Wastes Disposal Location:

Agencies Involved: Local Law Enforcement State Highway Patrol

Updates

Date: 5/13/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 13:10 p.m. The weather was partly cloudy, 48°F, with the wind from the southeast 5-10 mph. There is a small stained area in the middle of the highway lane going south a couple of miles. The produced water stayed in the middle of lane. The company made an effort to soak up the brine with sand. No further followup needed at this time.

Date: 5/13/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to incident report, release impacted area off location. Followup is required.