

Oil Field Environmental Incident Summary

Incident: 20150522095852 **Date/Time of Notice:** 05/22/2015 09:58

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: FRITZ "A" 1

Field Name: TREE TOP

Well File #: 7352

Date Incident: 5/21/2015 **Time Incident:** 17:00

Facility ID Number:

County: BILLINGS

Twp: 142 **Rng:** 100 **Sec:** 22 **Qtr:**

Location Description: Hayfield

Submitted By: Derek Enderud

Received By:

Contact Person: Derek Enderud
PO BOX 935
BISMARCK, ND 58502

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	15	Barrels			15	barrels

Description of Other Released Contaminant:

Emulsion.

Inspected:

Written Report Received: 5/29/2015

Clean Up Concluded: 5/28/2015

Risk Evaluation:

None.

Areal Extent:

Potential Environmental Impacts:

Topsoil is affected.

Action Taken or Planned:

Well was shut down and site is being cleaned up now. Pipeline will be repaired once cleanup is done.

Wastes Disposal Location: Chimney Butte Landfill

Agencies Involved:

Updates

Date: 5/22/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 7/16/2015 **Status:** Awaiting Documentation

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Awaiting document from landowner.

Date: 7/16/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received post clean-up report.

Date: 7/16/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 9:15 a.m. The weather was sunny, 60°F, with the wind from the northwest 5-10 mph. I talked to the person who was listed as the contact on the spill report. The break occurred northeast of the pad in the hay field. It was indicated that the landowner was satisfied with clean-up. I requested documentation from landowner to verify his/her satisfaction. The area along the pipeline right of way is vegetated. No more follow-up needed at this time.

Date: 10/30/2015 **Status:** No Further Action Requested

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received approval documentation from landowner; see report folder. No further followup required at this time.