

Oil Field Environmental Incident Summary

Incident: 20150618151950 **Date/Time of Notice:** 06/18/2015 15:19

Responsible Party: HESS CORPORATION

Well Operator: HESS CORPORATION

Well Name: BLMU CTB

Field Name: BEAVER LODGE

Well File #:

Date Incident: 6/18/2015 **Time Incident:** 09:50 **Facility ID Number:** 400045-06

County: WILLIAMS **Twp:** 156 **Rng:** 95 **Sec:** 32 **Qtr:** SW SW

Location Description: VRU building on location, initial inspection has indicated a bearing inside the recycle pump failed generating too much heat resulting in a small fire inside the building.

Submitted By: Troy Brunsell

Received By:

Contact Person: Jason Henry
3015 16TH ST SW STE 20
MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Fire was extinguished, inlet / outlet valves were isolated until repairs are made.

Areal Extent:

Potential Environmental Impacts:

Fire inside the VRU building

Action Taken or Planned:

Fire was extinguished, inlet / outlet valves were isolated until repairs are made.

Wastes Disposal Location: No waste to report at this time.

Agencies Involved:

Updates

Date: 6/18/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire on location. Nothing released off location according to the report. NDIC retains oversight.