

Oil Field Environmental Incident Summary

Incident: 20150710144750 **Date/Time of Notice:** 07/10/2015 14:47

Responsible Party: Pioneer Energy Services

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: PATTERSON 1-13H

Field Name: CAMP

Well File #: 20629

Date Incident: 7/10/2015

Time Incident: 08:30

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 100

Sec: 13

Qtr:

Location Description:

Submitted By: Justin Collins

Received By:

Contact Person: Justin Collins

14195 US-2

Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

1.5

Barrels

1.5

Barrels

Description of Other Released Contaminant:

Hydraulic Fluid

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Replaced filter, will remove contaminated soil once rig is removed

Wastes Disposal Location: TBD

Agencies Involved:

Updates

Date: 7/10/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill remained on location. NDIC retains oversight.