

Oil Field Environmental Incident Summary

Incident: 20150713220415 **Date/Time of Notice:** 07/13/2015 22:04

Responsible Party: SAMSON RESOURCES COMPANY

Well Operator: SAMSON RESOURCES COMPANY

Well Name: THOMTE 0508-3H

Field Name: AMBROSE

Well File #: 23590

Date Incident: 7/12/2015 **Time Incident:** 18:00

Facility ID Number:

County: DIVIDE

Twp: 164

Rng: 99

Sec: 32

Qtr:

Location Description: well pad

Submitted By: Brad Rogers

Received By:

Contact Person: Randy Landsverk
370 17TH ST. SUITE 2900
DENVER, CO 80202-5612

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	80	Barrels	40	Barrels	65	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/22/2015

Clean Up Concluded: 7/12/2015

Risk Evaluation:

no immediate risks identified from release. All produced water stayed on well pad

Areal Extent:

30' x 300'

Potential Environmental Impacts:

impact to soils on well pad from salt water

Action Taken or Planned:

well shut-in to stop produced fluids. A vacuum truck was brought to location to remove the produced water from the well pad surface. Impacted soils will be evaluated for either excavation and disposal of impacted soils or in-situ treatment

Wastes Disposal Location: Any impacted soils removed will be disposed of at an approved disposal facility (Secure 13-Mile Facility or R360 Smokey Butte Disposal)

Agencies Involved:

Updates

Date: 7/14/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.