

Oil Field Environmental Incident Summary

Incident: 20150802113741 **Date/Time of Notice:** 08/02/2015 11:37

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: RINDEL 17-162-95H

Field Name: BAUKOL NOONAN

Well File #: 17442

Date Incident: 8/1/2015 **Time Incident:** 12:00

Facility ID Number:

County: DIVIDE

Twp: 162 **Rng:** 95 **Sec:** 17 **Qtr:**

Location Description:

Submitted By: Timothy Ilse

Received By:

Contact Person: Lane Titus
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels	3	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/17/2015

Clean Up Concluded: 8/3/2015

Risk Evaluation:

None

Areal Extent:

N/A

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Contaminated material will be removed and replaced with clean fill. Recycle line connection will be replaced.

Wastes Disposal Location: R360

Agencies Involved: Called Jason Hicks @ 11:36 a.m. on 8/2/2015 left Voice Mail

Updates

Date: 8/3/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.