

Oil Field Environmental Incident Summary

Incident: 20150805114009 **Date/Time of Notice:** 08/05/2015 11:40
Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC
Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC
Well Name: STOMPING HORSE SERVICE WELL 2
Field Name: MCGREGOR **Well File #:** 90326
Date Incident: 8/5/2015 **Time Incident:** 02:30 **Facility ID Number:**
County: WILLIAMS **Twp:** 158 **Rng:** 95 **Sec:** 21 **Qtr:**

Location Description:

Submitted By: Tapan Souther **Received By:**
Contact Person: Tapan Souther
1200 17TH STREET, SUITE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine

Other

Description of Other Released Contaminant:

Produced gas used as fuel for electric generation.

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

None.

Areal Extent:

Incident was contained on wellsite location. No liquids were released.

Potential Environmental Impacts:

None.

Action Taken or Planned:

Supply gas line located near flare will be replaced with a steel line.

Wastes Disposal Location: No wastes to be recovered.

Agencies Involved:

Updates

Date: 8/5/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire, remained on location according to the report. NDIC retains oversight.