

Oil Field Environmental Incident Summary

Incident: 20150811080958 **Date/Time of Notice:** 08/11/2015 08:09

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: MARIANA TRUST 12X-20H

Field Name: NORTH FORK

Well File #: 23266

Date Incident: 8/10/2015 **Time Incident:** 09:30

Facility ID Number:

County: MCKENZIE

Twp: 149

Rng: 97

Sec: 20

Qtr:

Location Description: Spill was contained in a metal lined berm

Submitted By: Jeremy Waldschmidt

Received By:

Contact Person: Cody Knetzger
P.O Box 6501
Englewood, CO 80155

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 10 | Barrels | 10 | Barrels | | |

Brine

Other

Description of Other Released Contaminant:

N/A

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None - contained in berm

Areal Extent:

N/A

Potential Environmental Impacts:

None - contained in metal lined berm and picked up immediately.

Action Taken or Planned:

Spill was contained in a metal lined berm, free standing liquids were sucked up and placed back into the tanks

Wastes Disposal Location: Liquids will be sucked up and placed back into the production tank.

Agencies Involved:

Updates

Date: 8/11/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained within the diking according to the report. NDIC retains oversight.