

Oil Field Environmental Incident Summary

Incident: 20150813110047 **Date/Time of Notice:** 08/13/2015 11:00

Responsible Party: TUSA

Well Operator: TRIANGLE USA PETROLEUM CORPORATION

Well Name: WAHLSTROM 152-102-34-27-1H

Field Name: ELK

Well File #:

Date Incident: 8/9/2015 **Time Incident:** 00:00 **Facility ID Number:** 228172-01

County: MCKENZIE **Twp:** 151 **Rng:** 102 **Sec:** 3 **Qtr:** LO T3

Location Description:

Submitted By: Brittany Vannoy

Received By:

Contact Person: Brittany Vannoy
1200 17TH ST., SUITE 2600
DENVER, CO 80202-5826

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|--------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | | | | | | |
| Brine | | | | | | |
| Other | 15 | Barrels | 15 | Barrels | | |

Description of Other Released Contaminant:

Produced water

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None.

Areal Extent:

Potential Environmental Impacts:

None.

Action Taken or Planned:

Fluid was sucked up and placed into production tanks.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 8/13/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, was contained on the facility site according to the report. NDIC retains oversight.