

Oil Field Environmental Incident Summary

Incident: 20150815204639 **Date/Time of Notice:** 08/15/2015 20:46

Responsible Party: ENERPLUS RESOURCES USA CORPORATION

Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: ETHAN HALL 6B-7-1H

Field Name: MOCCASIN CREEK

Well File #: 18545

Date Incident: 8/14/2015 **Time Incident:** 22:00

Facility ID Number:

County: DUNN

Twp: 147

Rng: 93

Sec: 6

Qtr: NW NE

Location Description: Well pad and adjacent prairie.

Submitted By: Tony Lucero

Received By:

Contact Person: Chuck Antle
US BANK TOWER
950 17TH ST STE 2200
DENVER, CO 80202

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.8	Barrels			0	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/25/2016

Clean Up Concluded: 9/4/2015

Risk Evaluation:

Potential ignitability hazard.

Areal Extent:

Extent of release is under investigation.

Potential Environmental Impacts:

Contamination of adjacent pasture land.

Action Taken or Planned:

Shut well in. Cut impacted grass for offsite disposal at an approved facility.

Wastes Disposal Location: At an approved disposal facility.

Agencies Involved: BLM, BIA and Three Affiliated Tribes.

Updates

Date: 8/17/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred within the MHA Nation borders. Forward to BIA/Tribal authorities.