

Oil Field Environmental Incident Summary

Incident: 20150821094122 **Date/Time of Notice:** 08/21/2015 09:41

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: HARTFORD 1-19H

Field Name: DOLLAR JOE

Well File #: 19565

Date Incident: 8/20/2015 **Time Incident:** 14:00

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 97

Sec: 19

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Shane Knuchel
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

No fluid released.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Fire

Areal Extent:

An estimated 300 acres of stubble field was burned north and north west of the well site.

Potential Environmental Impacts:

Vegetation

Action Taken or Planned:

Fire was extinguished.

Wastes Disposal Location: N/A

Agencies Involved: Local Fire Department; Epping Fire Department/Ray Fire Department
Notified Jonathan Rumppe NDIC by phone on 8/20/2015 at 5:00 PM

Updates

Date: 8/21/2015 **Status:** Reviewed - Follow-up Required

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Incident involved a fire with no fluids impacting the soil. Off the well pad, soil was affected by the fire. Followup is required for site. Approximately one-half section was affected by the fire. The rural fire department responded, and the fire was extinguished. The cause of the fire is still under investigation.

Date: 8/25/2015 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 8/25/2015, at 1:45 p.m. Area impacted off location was a stubble field north of well pad. Field is burned to the ground. There does not appear to be any fluid impacting area. Remaining impact consists of burnt stubble. No further followup required.

Date: 3/11/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 11, 2016.