

Oil Field Environmental Incident Summary

Incident: 20150829124709 **Date/Time of Notice:** 08/29/2015 12:47

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: MPHU 21-15

Field Name: MEDICINE POLE HILLS

Well File #: 13602

Date Incident: 8/28/2015 **Time Incident:** 14:02

Facility ID Number:

County: BOWMAN

Twp: 130

Rng: 104

Sec: 15

Qtr:

Location Description:

Submitted By: Timothy Ilse

Received By:

Contact Person: Cory Irons
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels			0.5	barrels
Brine	0.5	Barrels			0.5	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 12/29/2016

Clean Up Concluded: 9/7/2015

Risk Evaluation:

None

Areal Extent:

6 ft. by 8 ft. area

Potential Environmental Impacts:

Topsoil and vegetation

Action Taken or Planned:

One call was placed then clean-up will conclude weather permitting. All visibly contaminated material will be removed and replaced with clean-fill.

Wastes Disposal Location: Little Missouri Landfill

Agencies Involved: Called Allan Christensen @ 12:30 8/29/2015

Updates

Date: 8/31/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a pipeline leak, impacted areas off location. Followup is required.

Date: 12/18/2015 **Status:** Inspection

Author: Cooper, Mike

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site, 9:30 a.m. 5 degrees, wind 0-5 mph NE. Walked around entire site; snow cover made it difficult to locate pipeline right of way (ROW). Evidence of grazing in the area surrounding the well before snowfall. Spill site is located next to Medicine Pole Hills processing plant. Did not see any evidence of a pipeline row leading away from site. Searched in area surrounding site and could not find evidence of pipeline row. Further followup is necessary when snow cover isn't an issue, checking for disposal and evidence of vegetative growth within the vicinity of pipeline ROW.

Date: 6/3/2016 **Status:** Inspection

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited the site on 4/25/16 at 11:15 a.m. Vegetation in the impact area appears healthy with no signs of salt stress. NO FURTHER ACTION IS WARRANTED.

Date: 6/6/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.