

# Oil Field Environmental Incident Summary

**Incident:** 20150923100052      **Date/Time of Notice:** 09/23/2015 10:00

**Responsible Party:** OXY USA INC.

**Well Operator:** OXY USA INC.

**Well Name:** NEAL 1-33-28H-144-95

**Field Name:** MURPHY CREEK

**Well File #:** 18300

**Date Incident:** 9/22/2015      **Time Incident:** 09:45

**Facility ID Number:**

**County:** DUNN

**Twp:** 143

**Rng:** 95

**Sec:** 4

**Qtr:**

**Location Description:**

**Submitted By:** Robyn Espinoza

**Received By:**

**Contact Person:** Robyn Espinoza  
5 GREENWAY PLAZA STE 110  
HOUSTON, TX 77046-0506

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	Barrels	2	Barrels	2	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/20/2015

**Clean Up Concluded:** 9/23/2015

**Risk Evaluation:**

Contaminated surface material

**Areal Extent:**

**Potential Environmental Impacts:**

Contaminated surface material

**Action Taken or Planned:**

A vac truck was immediately dispatched to recover all standing liquids, the operator removed and properly disposed of all other contaminated materials

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 9/23/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to stuffing box leak, remained on location according to the report. NDIC retains oversight.