

Oil Field Environmental Incident Summary

Incident: 20150926120543 **Date/Time of Notice:** 09/26/2015 12:05

Responsible Party: ARMSTRONG OPERATING, INC.

Well Operator: ARMSTRONG OPERATING, INC.

Well Name: S. E. RUSSIAN CREEK 42-18 SWD

Field Name: SIMON BUTTE

Well File #: 90076

Date Incident: 9/26/2015 **Time Incident:** 08:00

Facility ID Number:

County: DUNN

Twp: 141

Rng: 95

Sec: 18

Qtr:

Location Description:

Submitted By: Devin Carlson

Received By:

Contact Person: Devin Carlson
PO BOX 1999
513 ELKS DR
DICKINSON, ND 58602-1999

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine	60	Barrels	60	Barrels		
--------------	----	---------	----	---------	--	--

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None expected at this time. Release contained within dike.

Areal Extent:

Potential Environmental Impacts:

None expected. Release was contained within dikes. Vac. truck was on location within 1 hour to recover released brine.

Action Taken or Planned:

Leak discovered by pumper Lloyd Lindbo. Called Rick Hutchins with NDIC upon discovery. James Oil Well Service was called for vac. truck. Production water was removed from inside dikes. Remaining water in tank will be removed with vac. truck. Inspection of tank will occur to identify where tank failed. Repairs will be made to tank if possible or tank will be replaced.

Wastes Disposal Location: Recovered production water and remaining production water removed from tank will be taken to nearest Salt Water Disposal.

Agencies Involved:

Updates

Date: 9/28/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained within dike, according to the report. NDIC retains oversight.