

# Oil Field Environmental Incident Summary

**Incident:** 20151020092914      **Date/Time of Notice:** 10/20/2015 09:29

**Responsible Party:** PETROGULF CORPORATION

**Well Operator:** PETROGULF CORPORATION

**Well Name:** THREE TRIBES 151-94-4HTF

**Field Name:** ANTELOPE

**Well File #:** 28523

**Date Incident:** 10/19/2015      **Time Incident:** 08:00

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 151

**Rng:** 93

**Sec:** 31

**Qtr:** SW SE

**Location Description:**

**Submitted By:** Jerry Goedert

**Received By:**

**Contact Person:** Jerry Goedert  
518 17TH ST STE 1525  
DENVER, CO 80202

**General Land Use:** Cultivated

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

<b>Brine</b>	5	Barrels				
--------------	---	---------	--	--	--	--

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No immediate health risk

**Areal Extent:**

Spill occurred entirely inside the stock tank containment

**Potential Environmental Impacts:**

Spill occurred inside the stock tank containment. No impact to surface water, soil, or groundwater is possible

**Action Taken or Planned:**

It is planned to have a vacuum truck recover the spilled water

**Wastes Disposal Location:** Recovered water will be disposed at a produced water disposal facility, such as the 1804 facility.

**Agencies Involved:** MHA Energy

**Updates**

---

**Date:** 10/20/2015 **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to valve/piping connection leak, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.