

Oil Field Environmental Incident Summary

Incident: 20151125202744 **Date/Time of Notice:** 11/25/2015 20:27

Responsible Party: STATOIL OIL & GAS LP

Well Operator: STATOIL OIL & GAS LP

Well Name: ZINE 12-1 #1H

Field Name: BULL BUTTE

Well File #: 21627

Date Incident: 11/25/2015 **Time Incident:** 13:00

Facility ID Number:

County: WILLIAMS

Twp: 156 **Rng:** 103 **Sec:** 12 **Qtr:**

Location Description:

Submitted By: Derrick McBride

Received By:

Contact Person: Derrick McBride
6300 BRIDGE POINT PKY, BLDG 2
SUITE 500
AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	100	Barrels	100	Barrels		

Description of Other Released Contaminant:

Fresh water

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk were identified

Areal Extent:

Potential Environmental Impacts:

No environmental impacts are likely to occur. The freshwater was not mixed with any other chemicals or substances.

Action Taken or Planned:

- All fluids remained on location and will be vacuumed up by a vacuum truck.
- Float inspection frequency will be increased due to the potential of floats "sticking" in freezing conditions.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 11/27/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on the constructed well site according to the report. NDIC retains oversight.