

Oil Field Environmental Incident Summary

Incident: 20151211005557 **Date/Time of Notice:** 12/11/2015 00:55

Responsible Party: Nuvera

Well Operator: BUCKHORN ENERGY SERVICES, LLC

Well Name: Vinger #1 SWD

Field Name: WHEELOCK

Well File #: 90212

Date Incident: 12/10/2015 **Time Incident:** 01:26

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 98

Sec: 21

Qtr: SE SE

Location Description:

Submitted By: Nancy Roberts

Received By:

Contact Person: Chris Murray
4607 2nd Ave W
Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2	Barrels	2	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None all fluid was picked up by vac truck

Areal Extent:

Potential Environmental Impacts:

No impact - all fluid picked up and all was contained on facility site

Action Taken or Planned:

All liquid was picked up and sent into system.

Wastes Disposal Location: Into the Vinger #1 SWD

Agencies Involved:

Updates

Date: 12/11/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on the facility site according to the report. NDIC retains oversight.