

Oil Field Environmental Incident Summary

Incident: 20160112070629 **Date/Time of Notice:** 01/12/2016 07:06

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: LOKKEN 4-2H

Field Name: STONEVIEW

Well File #: 21178

Date Incident: 1/11/2016 **Time Incident:** 11:30

Facility ID Number:

County: WILLIAMS

Twp: 160

Rng: 95

Sec: 35

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Shane Knuchel
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Gallons	5	Gallons	5	gallons

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 5/4/2016

Clean Up Concluded: 1/13/2016

Risk Evaluation:

None

Areal Extent:

10 ft x 40 ft off east side of well site facility was lightly misted.

Potential Environmental Impacts:

Topsoil and vegetation

Action Taken or Planned:

Impacted snow scraped up and put into the flare pit.

Wastes Disposal Location: Flare pit.

Agencies Involved: Notified Jonathan Rumppe NDIC by phone on 1/11/2016 at 3:26 PM CT.

Updates

Date: 1/12/2016 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/12/2016 at 15:20, on location. Multi-well pad. Impacted snow visible coming from flare pit located at northwest corner of wellpad, with mist heading directly southeast off location. Most prominent impact visible on the facility, with staining off location barely discernible. Cleanup has not yet started, so followup will be needed to confirm cleanup.

Date: 1/12/2016 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Follow-up is required.

Date: 4/11/2016 **Status:** Inspection

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited the site at 16:30 on 4/7/2016. Spoke with a Continental Resources employee who showed me the impact area. The vegetation has been mowed, and the site was beginning to re-vegetate. No visible signs of impact were present. No further action is warranted.

Date: 6/6/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.