

# Oil Field Environmental Incident Summary

**Incident:** 20160122151944      **Date/Time of Notice:** 01/22/2016 15:19  
**Responsible Party:** MARATHON OIL COMPANY  
**Well Operator:** MARATHON OIL COMPANY  
**Well Name:** BINGO CTB  
**Field Name:** REUNION BAY      **Well File #:**  
**Date Incident:** 1/22/2016      **Time Incident:** 08:15      **Facility ID Number:** 230681-01  
**County:** MOUNTRAIL      **Twp:** 151      **Rng:** 93      **Sec:** 10      **Qtr:** SW SW  
**Location Description:** Access Road and Reunion Bay Road

**Submitted By:** Callie Karrigan      **Received By:**  
**Contact Person:** Paul Beacham  
3172 HWY 22 N  
DICKINSON, ND 58601

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	Gallons	2	Gallons	2	gallons

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 2/1/2016      **Clean Up Concluded:** 1/22/2016

**Risk Evaluation:**  
No immediate risks.

**Areal Extent:**  
300 yards on lease road and Reunion Bay Road

**Potential Environmental Impacts:**

The release was cleaned up immediately to eliminate the risk of traffic spreading the release further or on vegetation.

**Action Taken or Planned:**

The affected snow area was cleaned and disposed. Trucking company is inspecting vehicles and re-enforcing operating procedures.

**Wastes Disposal Location:** Recovered snow was placed in the facility flare pit for future disposal.

**Agencies Involved:** MHA, TAT Environmental

**Updates**

---

**Date:** 1/22/2016    **Status:** Reviewed - Assigned to Other Agency    **Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to valve/piping connection leak, was not contained according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA and EPA.