

Oil Field Environmental Incident Summary

Incident: 20160125110718 **Date/Time of Notice:** 01/25/2016 11:07

Responsible Party: ENERPLUS RESOURCES USA CORPORATION

Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: MUSIC-CHORD CTB

Field Name: MCGREGORY BUTTES

Well File #:

Date Incident: 1/24/2016 **Time Incident:** 13:00 **Facility ID Number:** 221274-01

County: DUNN **Twp:** 148 **Rng:** 93 **Sec:** 18 **Qtr:** SW SE

Location Description:

Submitted By: Shannon Oliver

Received By:

Contact Person: Josh Ruffo
US BANK TOWER
950 17TH ST STE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pump Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Low risk, small amount of spilled material and contained within dike.

Areal Extent:

Less than one sq. yd.

Potential Environmental Impacts:

Low impact, small amount of spilled material and contained within dike.

Action Taken or Planned:

Recycle pump valve was closed to stop flow to the pump. Pump was unfrozen and returned to normal operation.

Wastes Disposal Location: Contaminated soil was removed to a temporary waste bin and will ultimately be hauled to an approved waste handling facility.

Agencies Involved:

Updates

Date: 1/25/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a pump leak, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.