

# Oil Field Environmental Incident Summary

**Incident:** 20160229164426      **Date/Time of Notice:** 02/29/2016 16:44

**Responsible Party:** MUREX PETROLEUM CORPORATION

**Well Operator:** MUREX PETROLEUM CORPORATION

**Well Name:** DWIGHT LUDWIG 13-24H

**Field Name:** WRITING ROCK

**Well File #:** 26207

**Date Incident:** 2/28/2016      **Time Incident:** 17:00

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 161

**Rng:** 101

**Sec:** 13

**Qtr:** NE NW

**Location Description:**

**Submitted By:** William Jansky

**Received By:**

**Contact Person:** Shannon Holter  
363 N. Sam Houston Pkwy. E.  
Suite 200  
HOUSTON, TX 77060

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	105	Barrels	100	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

The well was shut in pending equipment inspection. A vacuum truck was called to recover pooled oil inside the dikes. Impacted area to be scraped. Remediation to begin immediately.

**Wastes Disposal Location:** Fluid to production tank. Solids to Secure 13 mile corner.

**Agencies Involved:**

**Updates**

---

**Date:** 3/1/2016      **Status:** Reviewed - Assigned to Other Agency      **Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release was contained to the well pad. NDIC has oversight.

---

**Date:** 3/2/2016      **Status:** Inspection      **Author:** Torgerson, Brad

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Cleanup of the crude oil spill within the bermed area on location appeared necessary. No apparent crude oil release off of the well location.