

# Oil Field Environmental Incident Summary

**Incident:** 20160306001518      **Date/Time of Notice:** 03/06/2016 00:15  
**Responsible Party:** ENERPLUS RESOURCES USA CORPORATION  
**Well Operator:** ENERPLUS RESOURCES USA CORPORATION  
**Well Name:** HUDSON 13-21H  
**Field Name:** MANDAREE      **Well File #:** 20087  
**Date Incident:** 3/5/2016      **Time Incident:** 06:00      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 149      **Rng:** 94      **Sec:** 13      **Qtr:** NW NE

## Location Description:

**Submitted By:** Tony Lucero      **Received By:**

**Contact Person:** Chuck Antle  
US BANK TOWER  
950 17TH ST STE 2200  
DENVER, CO 80202

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 3 Mile

**Distance Nearest Water Well:** 3 Mile

**Type of Incident:** Tank Leak

**Release Contained in Dike:** Yes - On Constructed Well Site      **Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

<b>Brine</b>	8	Barrels	8	Barrels		
--------------	---	---------	---	---------	--	--

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:**      **Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

Release was completely contained on the well pad.

**Potential Environmental Impacts:**

Entire release remained contained on the well pad.

**Action Taken or Planned:**

Tank closed; free liquid vacuumed up; contaminated media was excavated and transported offsite for disposal at an approved facility.

**Wastes Disposal Location:** At an offsite approved disposal facility.

**Agencies Involved:** BIA, BLM, Three Affiliated Tribes

**Updates**

---

**Date:** 3/7/2016      **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank leak, remained on constructed well site according to the report. NDIC retains oversight.