

Oil Field Environmental Incident Summary

Incident: 20160316150406 **Date/Time of Notice:** 03/16/2016 15:04

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: MARLENE 42X-20G

Field Name: BLUE BUTTES

Well File #: 25549

Date Incident: 3/15/2016 **Time Incident:** 1530

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 95

Sec: 20

Qtr: SE NE

Location Description:

Submitted By: Kaylan Dirx

Received By:

Contact Person: Kaylan Dirx
P.O Box 6501
Englewood, CO 80155

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	41	Barrels	40	Barrels	40	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/17/2016

Clean Up Concluded: 3/29/2016

Risk Evaluation:

None-leak was isolated, free liquids recovered and returned to production tanks.

Areal Extent:

Potential Environmental Impacts:

None-leak was isolated, free liquids (40 BBLs) recovered and returned to production tanks.

Action Taken or Planned:

Leaking hammer union will be replaced.

Wastes Disposal Location: Free liquids returned to production tank, impacted material will be disposed at Chimney Butte Disposal.

Agencies Involved:

Updates

Date: 3/16/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on the constructed well site according to the report. NDIC retains oversight.