

Oil Field Environmental Incident Summary

Incident: 20160318162920 **Date/Time of Notice:** 03/18/2016 16:29

Responsible Party: ENDURO OPERATING, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: WEINMAN 1

Field Name: NORTHEAST FOOTHILLS

Well File #: 7641

Date Incident: 3/15/2016 **Time Incident:** 09:10

Facility ID Number:

County: BURKE

Twp: 161

Rng: 91

Sec: 7

Qtr:

Location Description:

Submitted By: Scott Hunskor

Received By:

Contact Person: Scott Hunskor
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine	40	Barrels	40	Barrels		
--------------	----	---------	----	---------	--	--

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Shut in pump to stop leak, tanker truck on location to load fluid, skid steer and belly truck to haul off contaminated soil, wash off affected area with fresh water. Repair fitting.

Wastes Disposal Location: PDI in Tioga for solids, SWD tank for liquid

Agencies Involved:

Updates

Date: 3/18/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained within diking according to the report. NDIC retains oversight.