

Oil Field Environmental Incident Summary

Incident: 20160408124852 **Date/Time of Notice:** 04/08/2016 12:48
Responsible Party: WHITING OIL AND GAS CORPORATION
Well Operator: WHITING OIL AND GAS CORPORATION
Well Name: GULLIKSON 44-34H
Field Name: GLASS BLUFF **Well File #:** 32044
Date Incident: 4/7/2016 **Time Incident:** 16:30 **Facility ID Number:**
County: MCKENZIE **Twp:** 152 **Rng:** 103 **Sec:** 34 **Qtr:** SE SE
Location Description:

Submitted By: Corissa Zimmer **Received By:**
Contact Person: Corissa Zimmer
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 800 Feet
Distance Nearest Water Well: 800 Feet

Type of Incident: Treater Leak

Release Contained in Dike: No	Reported to NRC: No
Spilled Units Recovered Units Followup Units	
Oil 20 Gallons	15 gallons

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 4/29/2016 **Clean Up Concluded:** 4/8/2016

Risk Evaluation:

None noted.

Areal Extent:

The misted oil covered about 120' by 120' total, with about half over the fence to the south east.

Potential Environmental Impacts:

None noted.

Action Taken or Planned:

The spill was stopped and the plugged valve issue will be addressed. Whiting will plan clean up after discussion with the landowners, NDIC, and NDDoH.

Wastes Disposal Location: Any wastes will be disposed of at an approved facility.

Agencies Involved:

Updates

Date: 4/8/2016 **Status:** Reviewed - Follow-up Required **Author:** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Follow-up is required.

Date: 4/26/2016 **Status:** Inspection **Author:** Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

4/26/2016 at 12:34, on location. Multi-well pad. Treater units are located in NE corner of wellpad. Walked eastern fence of wellpad. Bordering wellpad on the other side of the facility fence is a field that has been plowed around its perimeter. No visible staining on the ground or on new vegetation growing on either side of the fence. No visible staining on the fence; however, area has had multiple days of heavy rainfall.

Date: 5/25/2016 **Status:** Inspection

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 1820. I observed bare ground along the western side of the pad. There is no vegetation due to pipeline installation; photos in the folder. Area of release was on east side of pad. I observed bare ground on that east side. Further follow-up needed to check on vegetation growth.