

Oil Field Environmental Incident Summary

Incident: 20160725181955 **Date/Time of Notice:** 07/25/2016 18:19

Responsible Party: Oneok Rockies Midstream

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 7/25/2016 **Time Incident:** 13:00

Facility ID Number:

County: MCKENZIE

Twp: 147 **Rng:** 104 **Sec:** 6 **Qtr:** SW

Location Description:

Submitted By: Levi Weltikol

Received By:

Contact Person: Levi Weltikol
896 25th St SE
Sidney, MT 59270

General Land Use: Pasture

Affected Medium: Soil and Water

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: Yes

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	35	Gallons				

Description of Other Released Contaminant:

Natural Gas Condensate

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk at this time

Areal Extent:

roughly 50' diameter of dead vegetation.

Potential Environmental Impacts:

A small amount of condensate ran to edge of wetland near the leak. however there is no sheen and no immediate environmental impact beyond some dead vegetation.

Action Taken or Planned:

Line has been blocked in and blown down. erosion control will be put into place to ensure no more contaminate will reach the wetland. Further remediation to follow.

Wastes Disposal Location: certified landfill

Agencies Involved:

Updates

Date: 7/26/2016 **Status:** Inspection

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 1100. There is a 20 X 20 ft area of barren soil that has some condensate staining visible. There were a few small puddles on the way down the hill that showed a sheen. The drainage area did not have a visible sheen or staining. The drainage leads into a cattle pond where no sheen was observed. A Group 190 water sample was taken at the drainage location next to the release. Further follow-up with the responsible party on cleanup efforts is needed. Photos of this release can be found in the report folder.

Date: 7/26/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, 35 gallons of natural gas condensate impacted soil and water along a pipeline right-of-way. More follow-up needed.