

Oil Field Environmental Incident Summary

Incident: 20160803183926 **Date/Time of Notice:** 08/03/2016 18:39

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: AMUNDSON CENTRAL TANK BATTERY

Field Name: SIVERSTON

Well File #:

Date Incident: 8/3/2016 **Time Incident:** 03:00 **Facility ID Number:** 229057-01

County: MCKENZIE **Twp:** 151 **Rng:** 98 **Sec:** 22 **Qtr:** SW SE

Location Description:

Submitted By: JORDAN WOLF

Received By:

Contact Person: Matt Olson
P.O Box 6501
Englewood, CO 80155

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

Spilled	Units	Recovered	Units	Followup	Units
----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/29/2016

Clean Up Concluded: 8/19/2016

Risk Evaluation:

Minimal- fire remained on location.

Areal Extent:

Fire remained on location.

Potential Environmental Impacts:

None- fire remained on location.

Action Taken or Planned:

All the wells were shut in immediately and the local fire department was onsite to extinguish the fire.

Wastes Disposal Location: N/A

Agencies Involved: Local Fire Department

Updates

Date: 8/3/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 12:43 p.m. Weather was sunny with wind out of the west 15 to 20 mph and temperature 93 degrees F. Walked the area on the pad and outside of the pad to the west and north. The wind pushed the oil from the flare fire to the NW across the pad. Observed small and very few oil droplets on the fence posts. Very little spray left the site. No water in the area due to dry conditions. NDIC retains oversight.