

General Environmental Incident Summary

Incident: 1211 **Date/Time Notice:** 1/11/2010 1221 **DEM Incident No:**
Responsible Party: American Crystal Sugar Company
Date Incident: 1/9/2010 **Time Incident:** 1600 **Duration:** 10 minutes
County: Pembina **Twp:** 159 **Rng:** 51 **Sec:** 14 **Qtr:**
Lat: 48.59303 **Long:** -97.17905 **Method:** Derived from TRS
Location Description: 8152 County Highway 44 North, Drayton, ND
Drayton, ND 58225-0190

Submitted By: Steve Lindquist **Affiliation:**

Address:

City: **State:** **Zip:**

Received By:

Contact Person: Steve Lindquist
8152 County Highway 44 North
PO Box 190
Drayton, ND 58225-0190

Distance Nearest Occupied Building: 2 Miles

Type of Incident: Pipeline Leak

Description of Released Contaminant: Beet Molasses

Volume Spilled: 2000.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Extreme cold weather caused the pipe to Molasses Loading to freeze. Attempts to thaw the pipe caused the end of the pipe to fail spilling the molasses.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

The molasses was absorbed with dry beet pulp. It will be scooped up with a payload.

Wastes Disposal Location: The pulp/molasses mix will be applied to the land west of the Mud Pond. When the soil thaws, it will be worked in.

Agencies Involved:

