

General Environmental Incident Summary

Incident: 192 **Date/Time Notice:** 12/6/1993 1442 **DEM Incident No:**

Responsible Party: Western Area Power Administration

Date Incident: 12/3/1993 **Time Incident:** 1000 **Duration:**

County: Burleigh **Twp:** 139 **Rng:** 76 **Sec:** 23 **Qtr:**

Lat: 46.84384 **Long:** -100.23580 **Method:** Derived from TRS

Location Description: 3 MILES EAST OF STERLING BY I94.

Submitted By:

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Patricia Dressler

Bismarck, ND

Distance Nearest Occupied Building:

Type of Incident: HYDROCARBON

Description of Released Contaminant: Transmission Fluid

Volume Spilled: 3.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance:

Reported to NRC: No

Cause of Incident:

LINE TRUCK WENT INTO SLOUGH. SHEEN WAS NOTED AFTER TRUCK WAS REMOVED.

Risk Evaluation:

of Fatalities:

of Injuries:

Affected Medium:

Potential Environmental Impacts:

Action Taken or Planned:

Wastes Disposal Location:

Agencies Involved:

