

General Environmental Incident Summary

Incident: 1936 **Date/Time Notice:** 6/7/2013 0815 **DEM Incident No:**

Responsible Party: LT Enterprises

Date Incident: 6/7/2013 **Time Incident:** 0815 **Duration:** 2 hours

County: McKenzie **Twp:** 152 **Rng:** 96 **Sec:** 26 **Qtr:**

Lat: 47.95588 **Long:** -102.93050 **Method:** Derived from TRS

Location Description: Mile marker 26 on Hwy 23 between Keene corner and the Keene Cenex on the east side of the road.

Submitted By: Jeff Wright

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Jeff Wright
1212 4th Ave NE
PO Box 1229
Watford City, ND 58854

Distance Nearest Occupied Building: 600 Feet

Type of Incident: Vehicle Accident

Description of Released Contaminant: Crude Oil

Volume Spilled: 14.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

Rollover accident

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

Brady Espe was dispatched to the scene and approved the clean-up work done by LT Enterprises. Brady Espe's number is 701-328-5228

Wastes Disposal Location: We have some other contaminated soil it will be disposed of with that at Chimney Butte Disposal. I informed Mr. Espe of our plan to disposal of the contaminated soil.

Agencies Involved: NDDDES, State Highway Patrol

Updates

Date: 6/7/2013 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

Their truck went over on the side spill out Bakken Crude. The trucking company was on scene shortly after it happened. The company transferred the rest of the oil to another truck. They cleaned up the highway with absorbent and scrape the absorbent up and placed into barrels to be disposed. The employees scraped up impacted grass and soil. The company had a vac truck suck up water and oil in ruts at the bottom of ditch. Nothing made it waters and the site look good. No more action was needed, future follow-up in not need at this time.

Date: 6/7/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Brady Espe was assigned to follow up on location.